ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar

Street ID	Street Name	Significant Landmark
W0755, W0695, W0751, W0749, W0614, W0763, W0691	NA, Cauveramma Street	devappa layout

Segment No.	Total Length (m)
11/S-W0755/S103446	401.30

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	167.07	77.549486	13.061230	77.551011	13.061020	I0163	W0691
2	117.00	77.550538	13.061041	77.550329	13.060004	W0614	DEAD END
3	117.23	77.550264	13.061063	77.550062	13.060022	W0614	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to main road and cross roads at devappa layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1500000	2014

Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	

Tender	Work Details	Job No. / Work Code
Not a Tender	Improvements to main road and cross roads at devappa layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-14-000023

Work Order No.	Work Order Date	Period of Extention
EE/BTP/KRIDL/WO/366/2014-15	24/03/2015	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
02/06/2015	01/06/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Phone No.	E-Mail ID

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
0		RANGANATH

Date of Inspection	Remarks
09/03/2017	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0755, W0695, W0751, W0749,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	09/03/2017	08/04/2017	COMPLETED
SE	VASU K M	09/03/2017	08/04/2017	COMPLETED
EE	SRINIVAS	09/03/2017	08/04/2017	COMPLETED
AEE	SRINIVASRU	09/03/2017	08/04/2017	COMPLETED
AE	RANGANATH	09/03/2017	08/04/2017	COMPLETED
AE	RANGANATH	09/03/2017	08/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0755, W0695, W0751, W0749,